	Туре	L#	Hits	Search Text	DBs
1	BRS	Ll	2245	(detect\$4 sens\$4 transducer meas\$4) near2 (misfir\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
2	BRS	L2	146	1 and (segment)	USPAT; US-PGPUB; EPO; JPO; DERWENT
3	BRS	L3	80	2 and (evaluat\$5 study\$4 examin\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
4	BRS	L4	22	3 and (shaft)	USPAT; US-PGPUB; EPO; JPO; DERWENT
5	BRS	L5	5	4 and (piston)	USPAT; US-PGPUB; EPO; JPO; DERWENT
6	BRS	L6	51	(evaluat\$5 study\$4 examin\$5) near2 (segment) near2 (time)	USPAT; US-PGPUB; EPO; JPO; DERWENT
7	BRS	L7	5	6 and (detect\$4 sens\$4 transducer meas\$4) near2 (misfir\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
8	BRS	L10	3	"5574290"	USPAT; US-PGPUB; EPO; JPO; DERWENT
9	BRS	L8	7	"5747679"	USPAT; US-PGPUB; EPO; JPO; DERWEN[T
10	BRS	L9	16	"5326986"	USPAT; US-PGPUB; EPO; JPO; DERWENT

-	Time Stamp	Comments	Error Definition	Erro rs
1	2003/09/16 13:12			0
2	2003/09/16 13:06			0
3	2003/09/16 13:12			0
4	2003/09/16 13:08			0
5	2003/09/16 13:08			0
6	2003/09/16 13:16			0
7	2003/09/16 13:13			0
8	2003/09/16 13:17			0
9	2003/09/16 13:17			0
10	2003/09/16 13:18			0